


SINCE 1958




TOTAL WELDING AND CUTTING SOLUTIONS

## POWER TIG 300DP<sub>III</sub>



## WELDING PROCEDURE PARAMETERS SELECTION AND SETTING



- 1- Pre-Flow ; Shielding gas pre-flow time ( sec.); in TIG ( GTAW ) welding mode; used for providing the shielding gas to the weld zone before the arc striking.
- 2- Hot-Start; In MMA ( SMAW ) welding mode; used for temporary increase of the output current during the start of weld.
- 3- Ignition Current; In TIG ( GTAW ) welding mode; used for setting the start current.
- 4- Up-Slope; In TIG ( GTAW ) welding mode; used for setting the time ( sec.) for the ignition current to the welding current.
- 5- Welding Current ; In TIG ( GTAW ) and MMA ( SMAW) welding modes; used for setting the welding current.  
Peak Current : In Pulse TIG ( GTAW ) welding mode; used for setting the peak current.
- 6- Pulse Ratio ; In Pulse TIG ( GTAW ) welding mode; used for setting the percentage ( %) time of the pulse frequency for welding current.
- 7- Frequency; In Pulse TIG ( GTAW ) welding mode; used for setting the pulse frequency in Hertz( Hz.)
- 8- Base- Current; In Pulse TIG ( GTAW ) welding mode; used for setting the TIG (GTAW) back-ground current.
- 9- Down-Slope; In TIG ( GTAW ) welding mode; used for setting the time ( in sec.) for the welding current to the crater current.
- 10- Crater Current; In TIG ( GTAW ) welding mode; used for setting the crater current at the end of down-slope .
- 11- Post-Flow ; Shielding gas post-flow time ( sec.); in TIG ( GTAW ) welding mode; used for providing the shielding gas to the weld zone after arc extinguished.
- 12- Arc – Force; In MMA (SMAW ) welding mode; it used for preventing the electrode from sticking during welding. Arc force is a temporary increase of the output current during welding when the arc is too short.

